



## Table of Contents

1 Introduction.....	2
2 Device Nomenclature.....	2
3 Device Markings.....	3
4 Advisory to Silicon Variant / Revision Map.....	4
5 Known Design Exceptions to Functional Specifications.....	5
6 Trademarks.....	16
Revision History.....	16

## 1 Introduction

This document describes the known exceptions to the functional and performance specifications to TI CMOS Radar Devices (AWRL1432 )

## 2 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of Radar / mmWave sensor devices. Each of the Radar devices has one of the two prefixes: XAx or AWRLx (for example: XA1432BGABL). These prefixes represent evolutionary stages of product development from engineering prototypes (XI) through fully qualified production devices AWRLx.

Device development evolutionary flow:

- XA** — Experimental device that is not necessarily representative of the final device's electrical specifications and may not use production assembly flow.
- AWRL** — Production version of the silicon die that is fully qualified.

XAx devices are shipped with the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

Texas Instruments recommends that these devices not to be used in any production system as their expected end –use failure rate is still undefined.

### 3 Device Markings

Figure 3-1 shows an example of the AWRL1432 Radar Device's package symbolization.




Figure 3-1. Example of Device Part Markings

This identifying number contains the following information:

- **Line 1:** TI Logo
- **Line 1:** Device Number
- **Line 2:** Safety Level and Security Grade
  - D = Deep Sleep Enabled
  - Q = Non-Functional Safety
- **Line 3:** Lot Trace Code
  - 27 = Year/Month Code
  - Z = Assembly Site Code
  - D6M = Assembly Lot
  - 9 = Primary Site Code
- **Line 4:**
  - 791A = Device Identifier
  - AMF = Package Identifier
  - G1 = "Green" Package Build (must be underlined)

## 4 Advisory to Silicon Variant / Revision Map

**Table 4-1. Advisory to Silicon Variant / Revision Map**

Advisory Number	Advisory Title	AWRL1432
		ES1.1
<b>Analog / Millimeter Wave</b>		
<a href="#">ANA #51</a>	Continuous Wave Streaming CZ mode: Sudden jump in RX output codes every 20.97152 msec	x
<a href="#">ANA #52</a>	Slicer LDO Test LOAD (TLOAD) not disabled after startup	x
<b>Digital Subsystem</b>		
<a href="#">DIG #1</a>	ePWM: Glitch during Chopper mode of operation	x
<a href="#">DIG #2</a>	UART: UARTA cannot be used to wake up the sequencer from Deep Sleep Low Power Mode	x
<a href="#">DIG #3</a>	UART: Limited UART baud rates	x
<a href="#">DIG #4</a>	RS232: AutoBaud Rate feature doesn't support trimmed RCOSC variation	x
<a href="#">DIG #6</a>	CRC: CRC 8-bit data width and CRC8-SAE-J1850 and CRC8-H2F possible use in CAN module is not supported	x
<a href="#">DIG #7</a>	APPSS Cortex-M4 doesn't get the correct error response when cluster 3 retention memories are accessed in low-power deep-sleep powered down state	x
<a href="#">DIG #8</a>	Shared RAM clock gating default values	x
<a href="#">DIG #9</a>	TOP_IO_MUX register space not accessible from RS232 for debug purposes	x
<a href="#">DIG #10</a>	Incorrect behavior of chirp stop in Infinite chirp mode	x

ADVANCE INFORMATION

## 5 Known Design Exceptions to Functional Specifications

**ANA #51**                      ***Continuous Wave Streaming CZ mode: Sudden jump in RX output codes every 20.97152 msec***

---

**Revision(s) Affected**    AWRL1432 ES1.1

**Details**                      On Continuous Wave Streaming CZ mode, the Rx data shows a sudden jump in output codes every 20.97152 milliseconds.

This is not an issue in the Radar Functional mode when chirps are used. However, this issue will be seen when testing Rx chain in lab using continuous stream mode.

**Workaround**                In order to use Continuous stream (CW) mode for testing, it is recommended to start data capturing from the first sample itself to make sure the glitch occurs at deterministic samples. Please follow the below sequence to achieve this:

- Configure the RDIF (Radar Data Interface)
- Arm the DCA1000 (Data capture card)
- Enable the continuous stream mode.

The glitch will not be seen with this sequence. For example, if the user analyzes first 20ms of data or between 21 and 41ms.

<b>ANA #52</b>	<b><i>Slicer LDO Test LOAD (TLOAD) not disabled after startup</i></b>
<b>Revisions Affected</b>	AWRL1432 ES1.1
<b>Details</b>	<p>By default, the slicer LDO TLOAD is enabled during startup for stability purposes. After the oscillator is enabled, the current loading should be disabled automatically to reduce power and extend reliability.</p> <p>Since presently the loading is not turned OFF automatically, higher than expected current is observed (~8mA).</p>
<b>Workaround</b>	<p>It is recommended to disable the load bit explicitly by setting the following field to save unnecessary power burnout :</p> <p>TOP_PRCM: CLK_CTRL_REG1_LDO_CLKTOP = 0x1</p>

**DIG #1** **ePWM: Glitch during Chopper mode of operation**

**Revision(s) Affected** AWRL1432 ES1.1

**Details** During chopper mode operation, a glitch may be observed on the ePWMA and ePWMB output signals from the ePWM module.

**Workaround** If the use case is impacted by a glitch, it is recommended to disable the PWM chopper control function by setting the LPRADAR:APP\_PWM:PCCTL:CHPEN register bit to 0.

The below table shows the Register Address for above workaround.

Bits	Name	Address
0	LPRADAR:APP_PWM:PCCTL:CHPEN	0X57F7 FC3C

**DIG #2** ***UART: UARTA cannot be used to wake up the sequencer from Deep Sleep Low Power Mode***

---

**Revision(s) Affected** AWRL1432 ES1.1

**Details** Universal Asynchronous Receiver-Transmitter A (UART A) cannot be used to wake up from Deep-Sleep mode of the processor. Currently UART B interrupts are connected to Wake-up Interrupt Controller lines.

**Workaround** It is recommended to use other wake-up sources (Local Interconnect Network(LIN)/ Controller Area Network - Flexible Data-rate (CAN-FD)/ UARTB/ Serial Peripheral Interface(SPI))

**ADVANCE INFORMATION**

**DIG #3** UART: Limited UART baud rates

**Revision(s) Affected** AWRL1432 ES1.1

**Details**

Due to a design limitation (related to the clocking scheme), UART doesn't support standard baud rates above 115200 bits per second. Higher baud rates up to 1.25Mbps can be supported but they are non-standard.

Applications requiring UART cannot use standard baud rates above 115200 bits per second

Standard Baud Rates supported :

XTAL (MHz)	40	
Ideal Baud rate (bps)	Actual Baud	Error %
115200	113636.36	1.36
76800	75757.58	1.36

Non- Standard baud rates supported:

<b>XTAL (MHz)</b>	<b>40</b>
Maximum baud (bps)	1250K
	833.33k
	625K
	500K
	416.66k
	357.14
	312.5k

**Workaround**

It is recommended to use the following workarounds based on application needs:

- Use of non-standard baud rates can provide up to 1.25Mbps throughput, if external MCU can support the same non-standard baud rates.
- LIN (without external LIN PHY) can function as a UART, and offer up to 576 Kbps.
- Use SPI instead, if use-case needs higher throughput.

**DIG #4** ***RS232: Auto Baud Rate feature doesn't support trimmed RCOSC variation***

---

**Revision(s) Affected** AWRL1432 ES1.1

**Details** Once RCOSC is trimmed, the expected clock frequency and the variation observed in frequency (tolerance on RC clock) do not support the required Auto Baud rate setting for RS232.

Currently Auto Baud is disabled by default for 14xx ES1.1

ADVANCE INFORMATION

---

<b>DIG #6</b>	<b><i>CRC: CRC 8-bit data width and CRC8-SAE-J1850 and CRC8-H2F possible use in CAN module is not supported</i></b>
<b>Revision(s) Affected</b>	AWRL1432 ES1.1
<b>Details</b>	CRC types CRC8-SAE-J1850 and CRC8-H2F are not supported for 8-bit data width. Minimum data width supported is 16-bit.
<b>Workaround</b>	It is recommended to not use the above mentioned unsupported polynomials.

<b>DIG #7</b>	<b><i>APPSS Cortex-M4 doesn't get the correct error response when cluster 3 retention memories are accessed in low-power deep-sleep powered down state</i></b>
<b>Revision(s) Affected</b>	AWRL1432ES1.1
<b>Details</b>	The logic to generate error when Cortex-M4F tries to access cluster 3 memories in powered down state is incorrect due to which Cortex-M4F doesn't get the correct error response.
<b>Workaround</b>	Software shouldn't try to access cluster 3 retention memories during low-power deep-sleep powered down state

**DIG #8** Shared RAM clock gating default values

**Revision(s) Affected** AWRL1432ES1.1

**Details**

Possibility of Shared RAM data corruption while exiting from deep sleep mode when clock gating registers are not reprogrammed.

The reset value for Front End Controller Sub System (FECSS), Application Sub System (APPSS) and Hardware Accelerator Sub System (HWASS) shared memory clock gate control is 1 . The clock ICG controls are coming from the following registers.

Bits	Name	Address
0	LPRADAR:FEC_CTRL:FECSS_SH ARED_MEM_CLK_GATE : FECSS_SHARED_MEM_CLK_GAT E_HWA_ENABLE	0x5200002C
0	LPRADAR:APP_CTRL:APPSS_SH ARED_MEM_CLK_GATE:APPSS_ SHARED_MEM_CLK_GATE_MEM 0_HWA_ENABLE	0x56060398
2	LPRADAR:APP_CTRL:APPSS_SH ARED_MEM_CLK_GATE:APPSS_ SHARED_MEM_CLK_GATE_MEM 1_HWA_ENABLE	0x56060398

When APPSS tries to access shared memory bank 0 via VBUSM SCR while FECSS is accessing shared memory via AHB, wrong read values of zero from the shared RAM on the APPSS is observed .

If only one of the clock gates (either HWA or FEC/APP) is enabled based on the allocation, the data is read correctly. Since the clock gating controls are coming from control registers space, these values get reset again and hence needs to be re-programmed after every deep sleep exit.

**Workaround**

Program ICG controls of clock reaching to shared memory based on different shared memory configuration. The ICG control needs to be re-programmed after every deep sleep exit too.

Configuration	Software care-about
Memory is shared with M3	Disable the following ICG control :- LPRADAR:FEC_CTRL:FECSS_SHARED_MEM_CLK _GATE : FECSS_SHARED_MEM_CLK_GATE_HWA_ENABLE
First 128kb is shared with M4	Disable the following ICG control :- LPRADAR:APP_CTRL:APPSS_SHARED_MEM_CLK _GATE:APPSS_SHARED_MEM_CLK_GATE_MEM0_ HWA_ENABLE
256kb is shared with M4	Disable the following ICG controls :- <ul style="list-style-type: none"> <li>• LPRADAR:APP_CTRL:APPSS_SHARED_MEM_ CLK_GATE:APPSS_SHARED_MEM_CLK_GATE _MEM0_HWA_ENABLE</li> <li>• LPRADAR:APP_CTRL:APPSS_SHARED_MEM_ CLK_GATE:APPSS_SHARED_MEM_CLK_GATE _MEM1_HWA_ENABLE</li> </ul>

**ADVANCE INFORMATION**

**DIG #9** **TOP\_IO\_MUX register space not accessible from RS232 for debug purposes**
**Revision(s) Affected** AWRL1432ES1.1

**Details** RS232 is not able to write TOP\_IO\_MUX registers unless the space is programmed for user mode access.

**Workaround** It is recommended to use the following sequence:

1. From Processor or DAP : Unlock TOP\_IO\_MUX registers (by programming LPRADAR:TOP\_IO\_MUX:IOCFGKICK0 = 83E7 0B13h and LPRADAR:TOP\_IO\_MUX:IOCFGKICK1 = 95A4 F1E0h )
2. From Processor or DAP : Write to TOP\_IO\_MUX registers, LPRADAR:TOP\_IO\_MUX:USERMODEEN should be set to 0xADADADAD
3. Now TOP\_IO\_MUX registers can be accessed from RS232.

The below table shows the Register Addresses for above workaround.

Bits	Name	Address
0:31	LPRADAR:TOP_IO_MUX:IOCFGKICK0	0x5A000068
0:31	LPRADAR:TOP_IO_MUX:IOCFGKICK1	0x5A00006C
0:31	LPRADAR:TOP_IO_MUX:USERMODEEN	0x5A000060

---

**DIG #10**                      ***Incorrect behavior of chirp stop in Infinite chirp mode***

---

**Revision(s) Affected**    AWRL1432ES1.1

**Details**                      In situations with infinite chirp mode, issuing a “*Chirp Stop*” command when frames are not in progress results in an incorrect behavior for the subsequent frame. The next frame starts to transmit normally, but stops after transmitting only one chirp.

**Workaround**                It is recommended to check the active status of the current frame and only issue chirp stop command if it is active

## 6 Trademarks

All trademarks are the property of their respective owners.

## Revision History

DATE	REVISION	NOTES
July 2023	*	Initial Release

## IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on [ti.com](https://www.ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265  
Copyright © 2023, Texas Instruments Incorporated